



**Weasler**

**LACK OF GREASE  
50° CV BALL & SOCKET**

These pictures show examples of damage caused by a lack of grease in a 50° constant velocity (CV) joint ball and socket.



**SOCKET YOKE**



**BALL YOKE**